ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0092, W0094, W0173, W0175	NA	Muslim colony in Jakkur
Segment No.	**Total Length (m)**	
7/C-W0092/S120111	288.20	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	54.80	77.604114	13.075052	77.604218	13.075536	RI-S50	W0094
2	158.29	77.602848	13.075222	77.604284	13.074986	DEAD END	DEAD END
3	75.11	77.603319	13.075699	77.603178	13.075034	RI-S50	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads in Muslim colony in Jakkur in ward no 07 Byatarayanapura Kodigehalli Sub-Division Yelahanka zone	1000000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Roads in Muslim colony in Jakkur in ward no 07 Byatarayanapura Kodigehalli Sub-Division Yelahanka zone	007-15-000014
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/267/2014-15	02/02/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
02/02/2015	01/02/2016	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
B M MUNIRAJU		0.00
Phone No.	**E-Mail ID**	

9886778826

Field Inspection Details

Number of Trees	Any Other Information	Name
0		BASAVARAJU

Date of Inspection	Remarks
26/11/2016	COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0092, W0094, W0173, W0175

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	27/11/2016	26/12/2016	COMPLETED
SE	VASU K M	27/11/2016	26/12/2016	COMPLETED
EE	SRINIVAS REDDY	27/11/2016	26/12/2016	COMPLETED
AEE	RAJINIKANTH MALLI	27/11/2016	26/12/2016	COMPLETED
AE	BASAVARAJU	27/11/2016	26/12/2016	COMPLETED
AE	BASAVARAJU	26/11/2016	26/12/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0092, W0094, W0173, W0175